

## Trail Access Information Summary

<b>Park Name</b>	Tucker French
<b>Trail Name</b>	French Connector
<b>Segment</b>	D to F
<b>Type</b>	
<b>Length</b>	0.3 mi (0.4 km)
<b>Elevation Gain</b>	9.0 ft (2.73 m)
<b>Elevation Loss</b>	34.1 ft (10.39 m)
<b>Trail Uses Allowed</b>	

### Trail Uses NOT Allowed

<b>Typical Grade</b>	3.3%	Max = 9.5%
Intermediate Maximum	Standard Ramp Grade is 8.3%	
<b>Typical Cross Slope</b>	4.4%	Max = 10.0%
Intermediate Maximum		
<b>Typical Tread Width</b>	24 in (61.0 cm)	Min = 24 in (61.0 cm)
Intermediate Minimum		
<b>Surface Type</b>	Soil	
<b>Surface Category</b>	0.0 % of Trail is Paved 0.0 % of Trail is Hard 100.0 % of Trail is Firm	0.0 % of trail is Soft 0.0 % of trail is Very Soft
<b>Firmness</b>	Typical: n/a	Minimum: n/a
<b>Stability</b>	Typical: n/a	Minimum: n/a

### Obstructions:

Type:	Size (Height):	Remaining Tread:	Location:
Rock	3 in (7.6 cm)	0 in (0.0 cm)	845.7 ft (257.8 m)
n/a	n/a in (n/a cm)	n/a in (n/a cm)	n/a (n/a m)
n/a	n/a in (n/a cm)	n/a in (n/a cm)	n/a ft (n/a m)

Warning: Trail conditions may have changed since when this trail was assessed. Temporary obstacles were not mapped.

Maximum grades and cross-slopes may vary. Obstructions less than ??? in (??? cm) or outside of the tread area 36 in (91.4 cm) wide by ??? in (??? cm) high were not reported. Minimum clearance width boundaries were at least ??? in (??? cm) high

Signage created by Beneficial Designs Inc. from data collected by a Certified Trail Assessment Coordinator using the High Efficiency Trail Assessment Process (HETAP).

Funded by: