Trail Access Information Summary

Park Name		Purloy Forms			
Trail Name		Burley Farms Blue Trail			
Segment		M to G			
Type		Linear	\		
Length		0.3 mi (0.4 km	,		
Elevation Gain		35.0 ft (10.66 r	•		
Elevation Loss		17.0 ft (5.19 m)			
Trail Uses Allowed		Bicycling - Mountain Snow - Snowshoeing		Snowshoeing	
		Hiking			
			Cross Country		
Trail Uses NOT Allowed		Equestrian			
		Motor Vehicles			
		Motor Vehicles	S -		
		Snowmobiling			
Typical Grade	_	3.8%		Max =	21.7%
	Intermediate				
	Maximum				
			p Grade is 8.3%		
Typical Cross Slope Intermediate Maximum		4.7%		Max = 12.6%	
Typical Tread Width		58 in (147.3 cm)		Min = 30 in (76.2 cm)	
Intermediate					
	Minimum				
Surface Type		Vegetation - M	own		
Surface Type Surface Category	у	Vegetation - M 0.0 % of Trail i		0.0 % c	of trail is Soft
	у	•	s Paved		of trail is Soft of trail is Very Soft
	у	0.0 % of Trail i	s Paved s Hard		
	у	0.0 % of Trail i 0.9 % of Trail i	s Paved s Hard		of trail is Very Soft
Surface Category	y	0.0 % of Trail i 0.9 % of Trail i 99.1 % of Trail	s Paved s Hard	0.0 % 0	of trail is Very Soft ım: n/a
Surface Category Firmness	y	0.0 % of Trail i 0.9 % of Trail i 99.1 % of Trail Typical: n/a	s Paved s Hard	0.0 % d	of trail is Very Soft ım: n/a
Surface Category Firmness Stability		0.0 % of Trail i 0.9 % of Trail i 99.1 % of Trail Typical: n/a	s Paved s Hard	0.0 % d	of trail is Very Soft ım: n/a
Surface Category Firmness Stability Obstructions:	Size (F	0.0 % of Trail i 0.9 % of Trail i 99.1 % of Trail Typical: n/a Typical: n/a	s Paved s Hard is Firm	0.0 % d	of trail is Very Soft Im: n/a Im: n/a
Firmness Stability Obstructions: Type:	Size (H 5 in (12	0.0 % of Trail i 0.9 % of Trail i 99.1 % of Trail Typical: n/a Typical: n/a	s Paved s Hard is Firm Remaining Tre	0.0 % d	of trail is Very Soft Im: n/a Im: n/a Location: 620.7 ft (189.2 m)
Firmness Stability Obstructions: Type: Step	Size (F 5 in (12 n/a in (0.0 % of Trail i 0.9 % of Trail i 99.1 % of Trail Typical: n/a Typical: n/a Height):	s Paved s Hard is Firm Remaining Tre 0 in (0.0 cm)	0.0 % d	of trail is Very Soft Im: n/a Im: n/a Location:

Warning: Trail conditions may have changed since 2023-03-13 when this trail was assessed. Temporary obstacles were not mapped.

Maximum grades and cross-slopes may vary. Obstructions less than <u>??? in (??? cm)</u> or outside of the tread area <u>36 in (91.4 cm)</u> wide by <u>??? in (??? cm)</u> high were not reported. Minimum clearance width boundaries were at least <u>??? in (??? cm)</u> high

Signage created by Beneficial Designs Inc. from data collected by a Certified Trail Assessment Coordinator using the High Efficiency Trail Assessment Process (HETAP).

Funded by: