

Trail Access Information Summary

Park Name	Howard Swain Memorial Forest
Trail Name	Quarry Trail
Segment	C to B-reversed
Type	
Length	0.4 mi (0.6 km)
Elevation Gain	95.6 ft (29.13 m)
Elevation Loss	47.2 ft (14.38 m)
Trail Uses Allowed	

Trail Uses NOT Allowed

Typical Grade	7.7%	Max = 31.6%
Intermediate Maximum	Standard Ramp Grade is 8.3%	
Typical Cross Slope	6.7%	Max = 27.8%
Intermediate Maximum		
Typical Tread Width	24 in (61.0 cm)	Min = 24 in (61.0 cm)
Intermediate Minimum		
Surface Type	Vegetation - Natural	
Surface Category	0.0 % of Trail is Paved 100.0 % of Trail is Hard 0.0 % of Trail is Firm	0.0 % of trail is Soft 0.0 % of trail is Very Soft
Firmness	Typical: n/a	Minimum: n/a
Stability	Typical: n/a	Minimum: n/a

Obstructions:

Type:	Size (Height):	Remaining Tread:	Location:
n/a	n/a in (n/a cm)	n/a in (n/a cm)	n/a ft (n/a m)
n/a	n/a in (n/a cm)	n/a in (n/a cm)	n/a (n/a m)
n/a	n/a in (n/a cm)	n/a in (n/a cm)	n/a ft (n/a m)

Warning: Trail conditions may have changed since 2024-06-10 when this trail was assessed. Temporary obstacles were not mapped.

Maximum grades and cross-slopes may vary. Obstructions less than ??? in (??? cm) or outside of the tread area 36 in (91.4 cm) wide by ??? in (??? cm) high were not reported. Minimum clearance width boundaries were at least ??? in (??? cm) high

Signage created by Beneficial Designs Inc. from data collected by a Certified Trail Assessment Coordinator using the High Efficiency Trail Assessment Process (HETAP).

Funded by: